

# Oil Field Environmental Incident Summary

**Incident:** 20160804153808      **Date/Time of Notice:** 08/04/2016 15:38

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** NESS 41-21XH CTB

**Field Name:** SANISH

**Well File #:**

**Date Incident:** 8/4/2016      **Time Incident:** 09:30      **Facility ID Number:** 220826-01

**County:** MOUNTRAIL      **Twp:** 154      **Rng:** 91      **Sec:** 21      **Qtr:** NE NE

**Location Description:**

**Submitted By:** Brian Wurm

**Received By:**

**Contact Person:** Brian Wurm  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.2 Mile

**Distance Nearest Water Well:** 0.2 Mile

**Type of Incident:** Treater Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	10	Barrels	10	Barrels	10	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 8/19/2016      **Clean Up Concluded:** 8/8/2016

**Risk Evaluation:**

None noted. Release stopped and fully contained

**Areal Extent:**

**Potential Environmental Impacts:**

Minimal, a vac truck has been brought in to pick up all free fluid and impacted material.

**Action Taken or Planned:**

Treater was isolated to stop further release. A vac truck was brought in to pick all fluid and impacted material. Approximately 10 bbls of oil and 30 bbls of rain water was removed from location.

**Wastes Disposal Location:** Impacted material will be taken to Secure Disposal facility

**Agencies Involved:****Updates**

---

**Date:** 8/4/2016      **Status:** Reviewed - Assigned to Other Agency      **Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the release remained on location. NDIC retains oversight.